



SAFETY NOTICE

Arc Flash Harness Recall

RISK MANAGEMENT & SAFETY

Date: June 2020
Category: Product Recall

Contact RMS:

Tel: 1-5037

IMMEDIATE ACTION REQUIRED

3M™ Fall Protection Specific DBI-SALA® Delta™ & Exo it XP™ Arc Flash Harnesses

3M has issued a [Stop Use Notice](#) regarding potential safety concerns with specific DBI-Sala fall protection harnesses. 3M's recent testing of specific DBI-SALA® Delta™ & Exofit XP™ Arc Flash harnesses has returned negative test re-sults on some units. The affected models' part numbers are included in the tables in the stop use notice (link [here](#)).

RMS is asking that you take the following actions:

1. Immediately inspect each of your harnesses to determine if you own any of the affected models. The harness part number can be found on the harness label.
2. Once complete, notify Mary Beth Greendonner (mgreendo@nd.edu) and Randy Crist (jcrist1@nd.edu) of your results.
3. If you identify that you have an affected harness, please:
 - Remove the affected harness from service.
 - Notify Marybeth Greendonner (mgreendo@nd.edu) & Randy Crist (jcrist1@nd.edu) of your results.
 - Inform 3M by contacting 3M Customer Service at 1-833-638-2697 or at 3musfbserviceaction@mmm.com. The company will contact you to discuss your options. A solution to this issue is expected this month.

https://www.3m.com/3M/en_US/worker-health-safety-us/safety-resources-training-news/safety-news/ppe-notifications-and-advisories/harness-dring-low-volume-product-advisory/

All safety communications can be found at <https://riskmanagement.nd.edu/communication/>.

Document #: 20-0012